

A0145/17 (Issued for HLLL) - UNDER THE AUTHORITY OF THE LIBYAN CIVIL AVIATION AUTHORITY THE FOLLOWING CONTINGENCY PROCEDURES FOR TRANSIT TFC IN THE HLLL FIR ARE APPLICABLE TAKING INTO ACCOUNT LIMITATIONS IN ATM/CNS AND SAFETY OF FLIGHT OPERATIONS.

THE PROCEDURES IN THIS NOTAM ARE MANDATORY AND SHALL BE STRICTLY ADHERED TO. PRIOR PERMISSION TO OPERATE INTO HL INTERNATIONAL AERODROMES AND TO OVERFLY HLLL FIR IS REQUIRED BY ADVANCE NOTIFICATION TO THE LIBYAN CAA ON EMAIL:ATD AT CAA.GOV.LY OR BY FAX +218213618075 OR ON AFTN: HLLTYAYA/HLLTYAYX.

HLLB(BENINA) HLLM (MITIGA),HLLQ (LABRAQ),HLMS (MISURATA),AND HLTQ (TOBRUK)ARE AVAILABLE H24 FOR INTERNATIONAL FLIGHTS AND EN-ROUTE DIVERSIONS.HLZW (ZWARA) IS ONLY AVAILABLE FOR NATIONAL FLIGHTS FROM SR TO SS.

MANDATORY ROUTING SCHEME FOR HLLL FIR OVERFLIGHTS. THE FWG ROUTES IN THE HLLL FIR ARE AVBL 24H FOR INTERNAIONAL TRAFFIC TRANSITING THE HLLL FIR. ALL OTHER ATS ROUTES ARE PROHIBITED FOR INTERNATIONAL TRANSIT TRAFFIC THROUGH THE HLLL FIR UFN. INTERNATIONAL FLIGHTS PLANNING TO OPERATE THROUGH THE HLLL FIR ARE ONLY PERMITTED TO FLIGHT PLAN IN ACCORDANCE WITH THE MANDATORY ROUTING SCHEME SPFCIFIED IN THIS NOTAM. DEVIATION FROM THESE ATS ROUTES IS ONLY ACCEPTED ON A TACTICAL BASIS AND WHEN REQUIRED FOR SAFETY AND OPERATIONAL REASONS. ANY INFORMATION ABOUT THE UNAVAILABILITY OF THE ATS ROUTES INDICATED BELOW WILL BE PROMULGATED BY NOTAM.

SOUTHBOUND /EASTBOUND ROUTES:

VIA ABRAM UN163 GRT A403 SEB UM214 GARIN
VIA ABRAM UN163 GRT A403 SEB A403F TUMMO
VIA ABRAM M727 ZAW UM727 DEKIL
VIA VARIG T299 ZAW UM600 IMN
VIA LOTIN UL12 TONBA
VIA FARES UM731 DEKIL
RASNO UY751 LOSUL
TANLI A411 PRAWN V400 LAB W861 NASER A411 LOSUL

NORTHBOUND/ WESTBOUND ROUTES:

VIA IMN UM600 ZAW M/UM600 SARKI
VIA TUMMO A403F SEB M740 SARKI
VIA GARIN UM214 SEB M740 SARKI
VIA GARIN UP126 LUMED
VIA TONBA UM215 LUMED
VIA DEKIL UM731 FARES
LOSUL UP128 LAB UM979 RAMLI UZ270 OLMAX
LOSUL UP128 TANLI

OPERATORS ARE REQUIRED TO USE THE IATA IN-FLIGHT BROADCAST PROCEDURE (IFBP) WHILE OPORATING IN THE HLLL FIR. PILOTS UNABLE TO MAINTAIN COMMUNICATION WITH ATC ARE REQUIRED TO ESTABLISH DIRECT PILOT-CONTROLLER COMMUNICATION ON THE DEDICATED TELEPHONE NUMBER +218215632331. WHEN COMMUNICATION ON THIS NUMBER IS NOT POSSIBLE PILOTS SHOULD ATTEMPT TO CONTACT ATC ON THE SECONDARY NUMBERS +218213619614.

18 DEC 12:55 2017 UNTIL 15 FEB 10:30 2018 ESTIMATED.
CREATED: 18 DEC 13:20 2017